Michael O. Leavitt Governor Robert L. Morgan Executive Director Lowell P. Braxton

1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City. Utah 84114-5801 (801) 538-5340 telephone (801) 359-3940 fax (801) 538-7223 TTY Lowell P. Braxton
Division Director

Www.nr.utah.gov

June 26, 2002

CERTIFIED RETURN RECEIPT 7099 3400 0016 8895 5286

Mr. Joseph Mike Caruso HC 65 Box 221 Pipe Springs, AZ 86022

Re: Notice of Potential Non-Compliance & Division Directive, Joseph Mike Caruso, ML

26996 & ML 41354, S/025/027, Kane County, Utah

Dear Mr. Caruso:

On March 11, 2002, we received a modified small mine permit transfer form for the Caruso Mine (file number S/025/007). The form was intended to transfer state Mineral Leases #ML 27618, ML 26996 and ML 41354 from Joe's Rock Shop (c/o Marie Caruso) to Joseph M. Caruso and Loy Crapo. The form indicated that the new operators would each have 50% ownership of State Lease #ML 27618 and ML 26996, and each operator would also have the right to mine both leases.

The small mine permit transfer was not finalized because current disturbed area maps of the lease areas were not included with the transfer form. On May 23, 2002, Tom Munson of the Minerals Program staff, performed an inspection and GPS survey of these mine areas. Mr. Munson also inspected a small pit that was portrayed as being within the Trail Canyon area on State Lease # ML 27618 (under Loy Crapo's file #S/025/025). After analyzing the GPS data collected during the onsite inspection, it has been determined that this small pit is not located on lease #ML 27618, but appears to be located on State Lease #ML 48588, which is held by Robert Harris (see attached map).

The disturbance that you have created on Lease #ML 48588 has not been properly permitted, nor has it been allowed by Mr. Robert Harris. Therefore, until you properly permit this new site, you are hereby directed to cease all mining and removal of material from this new area and immediately reclaim this disturbance, or negotiate some other arrangement/agreement with Mr. Harris within 30-days of your receipt of this letter. A copy of this agreement must be sent to the Division. If you wish to challenge our GPS measurements and findings, you may provide a certified survey of the site that demonstrates otherwise.



Page 2 Mike Caruso S/025/025 June 26, 2002

You are further directed to contact the Division within 10 days of your receipt of this letter to discuss options to remedy this situation. Please contact me at (801) 538-5286, or Tom Munson at 538-5321 in reply. Your failure to respond accordingly may result in the issuance of a formal Notice of Non-Compliance.

Subsequent negotiations have transpired since Mr. Munson's inspection and our receipt of the original permit transfer form, resulting in the following proposed changes to the transfer documents:

- 1. Mr. Crapo will be responsible for reclamation of all disturbances on ML 27618 (new file number S/025/025).
- 2. Mr. Caruso will be responsible for reclamation of all disturbances on combined leases ML 26996 and ML 41354 (new file number S/025/027).

Please sign and return the enclosed and revised Transfer Form within 10 days. These transfer forms have been filled out with the appropriate legal descriptions and have GPS disturbed area maps attached. When the permit transfers are complete, we will close and retire file S/025/007.

Thank you for your immediate attention to this matter.

Sincerely,

D. Wayne Hedberg Permit Supervisor

Minerals Regulatory Program

jb


Enclosures: DOGM GPS map, Revised MR-TRS form

cc: Eric Lind, Kane County Attorney, 34 N Main, Kanab, UT 84741 w/maps

Robert Harris, operator w/map Loy Crapo, operator w/maps Will Stokes, SITLA w/maps Tom Munson, DOGM


O:\M025-Kane\S025007Crapo-Caruso\final\potential noncomp - small mine.doc


Loy Crapo 50 % Mineral Owners Loy Crapo Mine Permit Holder S/025/025



Map produced on 6/13/02 by DOGM Data Source: GPS surveys of 6/14/2000 and 5/23/2002


Mike Caruso/ Loy Crapo 50 % Mineral Owners Mike Caruso Mine Permit S/025/027





Map Produced on 6/13/2000 by DOGM Data Source: GPS surveys of 6/14/2000 This Product may not meet DOGM standards for accuracy and content. Different data sources and input scales may cause some misalignment of data layers.

Tate lease # ML 269 Mike Caruso/ Loy Crapo 50 % Mineral Owners Mike Caruso Mine Permit S/025/027






Map Produced on 6/13/2000 by DOGM Data Source: GPS surveys of 6/14/2000

This Product may not meet DOGM standards for accuracy and content. Different data sources and input scales may cause some misalignment of data layers.

State Lease ML # 4.354 Mike Caruso Permit Holder S/025/027





Access Road -2639 feet




Mining Disturbance - .44 acres

Red Area disturbed by Mike Caruso in 1999 Inspection: June 13 and 14th, 2000

This Product may not meet DOGM standards for acurracy and content. Different data sources and input scales may cause some misalignment of data layers.

State Lease # ML 48586 Robert Harris Permit Holder S/025/006 (Mike Caruso Trespass)



NE/4 of NW/4 Section 36, T40 S, R7W

Quadrangle map: Orderville Inspection Date: 5/23/02 Inspector: Tom Munson